



3301 NW 55th Street, Ft. Lauderdale, FL 33309
Tel: (800) 544-8156

Certificate of Asbestos Analysis

Prepared for: XYZ Home Inspections
333 Miami Trail South
Sarasota, FL 34285

Phone: 444-444-3333
Email: you@homeinspections.com

Test Address: Phillip Matthews
3361 Palm Drive
Sarasota, FL 34231

Sample Number: Sample #1
Laboratory COC #: 0203444

Collection Location: Attic Insulation
Sample Description: Grey Fiberglass Wrap

Date Collected: 2/3/2015
Receive Date: 2/5/2015
Analysis Date: 2/6/2015
Report Date: 2/7/2015

Asbestos Results: 5% TREMOLITE ASBESTOS DETECTED

A handwritten signature in black ink, appearing to read "John D. Shane".

John D. Shane Ph.D., QA Manager

Samples analyzed by this test method are subject to the inherent limitations of EPA Method 600/M4-82-020. This report shall not be reproduced, except in full, without written permission from InspectorLab. This report contains data that were produced under subcontract to (NVLAP #123334-0)

All tests are subject to false positives and false negatives and the analyses and interpretation(s) made herein may not be regarded as a basis for taking any action regarding health or remediation of the tested materials.

For more information please contact InspectorLab at 800-544-8156
