


RADON REPROT

3709 Partridge Run

Delafield, Wisconsin 53018



RadStar RS300
 Radon Detector/Monitor
 Version 1.7
 Serial#: 03191
 Calib.#: 31965 Bkgnd03
 TestID#: 30136

Interval Report

Hour	T	B	AC	Alpha	pCi/L
001			0004		000.2
002			0026		001.4
003			0059		003.2
004			0058		003.1
005			0078		004.2
006			0085		004.6
007			0086		004.7

008	0104	005.6
009	0115	006.2
010	0102	005.5
011	0100	005.4
012	0086	004.7
013	0076	004.1
014	0086	004.7
015	0083	004.5
016	0074	004.0
017	0076	004.1
018	0095	005.1
019	0066	003.6
020	0087	004.7
021	0086	004.7
022	0100	005.4
023	0083	004.5
024	0097	005.3
025	0087	004.7
026	0095	005.1
027	0106	005.8
028	0115	006.2
029	0095	005.1
030	0083	004.5
031	0091	004.9
032	0082	004.4
033	0094	005.1
034	0096	005.2
035	0107	005.8
036	0093	005.0
037	0104	005.6
038	0111	006.0
039	0091	004.9
040	0088	004.8
041	0092	005.0
042	0086	004.7
043	0093	005.0
044	0096	005.2
045	0074	004.0
046	0098	005.3
047	0103	005.6
048	0080	004.3
049	0066	003.6
050	0083	004.5
051	0089	004.8
052	0097	005.3
053	0068	003.7

054	0081	004.4
055	0083	004.5
056	0093	005.0
057	0101	005.5
058	0094	005.1
059	0094	005.1
060	0093	005.0
061	0103	005.6
062	0104	005.6
063	0066	003.6

Avg: 004.9 pCi/L

Max: 006.2 pCi/L

Min: 003.6 pCi/L

The above tested property is ABOVE the EPA recommendation for residential radon and it is recommended the home be mitigated prior to sale.

Start Date/Time: Monday, April 13, 2015 at 5:44pm

End Date/Time: Thursday, April 16, 2015 at approximately 9:20am

Address: 3709 Partridge Run Delafield, Wisconsin 53018

Location of Instrument: Basement Per EPA Recommendation

Tested By: Tri County Home Inspection



TRI-COUNTY
HOME INSPECTION, LLC